Design Manufacturing Transactions Service	
Calibration tool	Issue Calibration failures causing rework and production delays. Failed pressure control units have to be disassembled by removing bellows, followed by a search for a replacement and a re-test. The rework process causes delays in shipments and overdue customer orders.

Breakthrough Strategy

- Measure A gage R&R study was conducted with two calibrators, and the bellows tester. The results indicated that operators were not a problem, rather the parts. Ten sample controller units and one master controller were calibrated, measured, and individually identified.
- Analyze Results of a Matrix Plot indicated that a dimension on the casting base has a critical interaction in calibration failure at 75%. The plot shows that one of the .795 dimensions that supports the bellows should be changed to .810.
- Improve Tally points, operator recording, and DPMO reporting were put in place. Calibration results are recorded daily and posted weekly. The reports are reviewed by the Process and Quality engineer.
- Control Base casting will produce a part within the 75% calibration range if one .795 +/- .005 dimension is at the high end of the tolerance of .810. A second gage R&R was done on the sample parts, indicating inconsistencies.
- Results Change the dimension from .795 to .810. A second dimension identified as the drilled hole pattern was reviewed for out-of-tolerance conditions. The section leader will also monitor the process, with results compared to a 50 week period from the previous year.
- Savings \$11,600 for replacement and retest, plus improved customer satisfaction for on-time deliveries.